



1




Eight (8) #8 X 3/8" machine screws

2




Four (4) M5 X 12mm hex flange head screws
Note: Second person required to help steady and keep shelves upright as they are installed.

3a




Two (2) M5 X 12mm hex flange head screws
Note: Second person required to help steady
and keep shelves upright as they are installed.

3b




Two (2) M5 X 12mm hex flange head screws
Note: Second person required to help steady
and keep shelves upright as they are installed.

4




5a




Eight (8) M5 X 12mm, hex flange head screws
 Note: Second person required to help steady
 and keep shelves upright as they are installed.

5b



Four (4) M5 X 12mm machine screws

6



Note: Two people required.

7



8

