

Qt100™ Software Upgrade Instructions

1. Upload Hex file (csmqt.com/support) to a new or empty USB flash drive.
2. If Qt 100 is plugged in, unplug.
3. Place USB with Hex file into USB port of the Qt100.
4. Wait 10 seconds after connecting USB.
5. Plug in the Qt 100.
6. Back light on LCD display will illuminate.
7. Rapid flashing will turn to a slow flash.
8. Once flashing ends "Booting Please Wait" will appear on LCD screen.
9. Display shows "Qt100 Main DSP Booting."
10. Display shows "Main DSP Loaded."
11. "Version" and "Status" will appear.
12. If Status shows "OK" remove USB from port.
13. Qt 100 Software upgrade complete.